I. Amendments to the Specification

Please amend some of the paragraphs in the specification as follows with the following clean versions of the paragraphs in accordance with 37 CFR § 1.121; marked-up versions of the paragraphs are presented in the following section.

Page 28, lines 21-31:

5

10

15

If the PXE Proxy service is executing, then a determination is made about whether or not the availability of the local server (absolute availability and/or relative availability) is below a lower threshold (step 406). If not, then the process branches to step 414. If the availability is below the lower threshold, then the Boot Monitor daemon requests the service manager to stop or suspend the PXE Proxy service (step 408). The manner in which the PXE Proxy service is suspended may vary depending upon several factors, such as the operating system of the local server.